

UNDERWATER BRIDGE INSPECTION REPORT

STRUCTURE NO. 57501
CSAH NO. 22
OVER THE
RED LAKE RIVER
DISTRICT 2 - PENNINGTON COUNTY



PREPARED FOR THE
MINNESOTA DEPARTMENT OF TRANSPORTATION
BY
COLLINS ENGINEERS, INC.
JOB NO. 5221 (CEI 162)

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

REPORT SUMMARY:

The substructure units inspected at Bridge No. 57501, Piers 1 and 2, were found to be in satisfactory to fair condition with undermining of the footing (base of shaft) and steel pile exposure at Pier 2. The concrete at the base of the piers below water was under reinforced and relatively soft with various spalls, cracks, and failed sections. The extent of the undermining and foundation pile exposure has been reduced at some locations since the previous inspection due to aggradation of the channel bottom material around the substructure units.

INSPECTION FINDINGS:


- (A) No design drawings were provided and it is assumed that the piers consist of a steel H-pile bent encased in concrete. The bottom of the encasement exhibited undermining exposing the easternmost steel H-piles at the upstream end of both piers with light surface corrosion. There was vertical face exposure of the footing (base of shaft step out at both piers) around entire perimeter of both piers, with 12 inches (full height) exposure around the upstream nose where the pile exposure was present.
- (B) A light to moderate accumulation of organics and/or timber debris was observed from the waterline to the channel bottom at the upstream end of Pier 1.
- (C) The concrete at the base of the pier shafts exhibited widespread irregularities due to section loss, with three corroded horizontal reinforcing bars exposed at the downstream end of Pier 1, as well as with cracks and areas of soft concrete at both piers.

RECOMMENDATIONS:

- (A) The extent of undermining and foundation pile exposure has been reduced since the last inspection, so based on the present state of things and the scour stable (low risk) rating for the bridge, it is only recommended that future inspections particularly monitor the undermining and pile exposure.
- (B) Reinspect the submerged substructure units at the normal maximum recommended (NBIS) interval of five (5) years.

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the State of Minnesota.


Daniel G. Stromberg



Date 6/30/2008 Registration No. 21491

Respectfully submitted,

COLLINS ENGINEERS, INC.



Daniel G. Stromberg
Registered Professional
Engineer, State of Minnesota

MINNESOTA DEPARTMENT OF TRANSPORTATION
UNDERWATER BRIDGE INSPECTION

1. BRIDGE DATA

Bridge Number: 57501

Feature Crossed: Red Lake River

Feature Carried: CSAH No. 22

Location: District 2 - Pennington County

Bridge Description: The bridge superstructure consists of three spans of multiple concrete box beams, which are supported by two concrete abutments and two concrete encased H-pile bent piers (assumed from field observations). The piers are numbered 1 and 2 starting from the south end of the bridge.

2. INSPECTION DATA

Professional Engineer Diver: Bradley A. Syler, P.E., S.E.

Dive Team: John J. Loftus, Valerie Rouston

Date: August 18, 2007

Weather Conditions: Sunny, 69° F

Underwater Visibility: 4.0 feet

Waterway Velocity: 1.5 f.p.s.

3. SUBSTRUCTURE INSPECTION DATA

Substructure Inspected: Piers 1 and 2.

General Shape: Field observations suggest that the piers are steel H-pile bent piers encased in a slender concrete shaft that steps out in a rectangular fashion (like a footing) at its base.

Maximum Water Depth at Substructure Inspected: Approximately 4.0 feet.

4. WATERLINE DATUM

Water Level Reference: The top of the pier bridge seat on the west side of Pier 1.

Water Surface: The waterline was approximately 10.9 feet below reference.
Assumed Waterline Elevation = 89.1 feet.

5. NBIS CODING INFORMATION (Minnesota specific codes are used for 92B and 113)

Item 60: Substructure: Code 5

Item 61: Channel and Channel Protection: Code 5

Item 92B: Underwater Inspection: Code B/08/07

Item 113: Scour Critical Bridges: Code I/94

Bridge is scour critical because abutment or pier foundation is rated as unstable due to observed scour at bridge site.


 Yes X No



Photograph 1. View of Pier 1, Looking North.



Photograph 2. View of Pier 2, Looking South.



GENERAL NOTES:

- Piers 1 and 2 were inspected at this bridge.
- At the time of inspection on August 18, 2007, the waterline was located approximately 10.9 feet below the top of the pile cap at the downstream end of Pier 1. Since insufficient bridge elevation information was available a reference elevation of 100.0 was assumed. Based on the assumed reference, the waterline elevation was 89.1.
- Soundings indicate the water depth at the time of inspection and are measured in feet.
- Soundings were taken parallel to the bridge at 1/4 point intervals between the substructure units.

SOUNDING PLAN

INSPECTION NOTES:

- The channel bottom material consisted of silty sand and gravel with scattered 6 to 8 inch diameter cobbles and up to 3 inches of probe rod penetration.
- A light to moderate accumulation of vegetation and organics with 6 inch diameter timber debris was observed from 1 foot above the waterline to the channel bottom and radiating 5 feet from the upstream nose of Pier 1.
- The bottom portion of the shaft (stepout) was broken off at the downstream end of Pier 1 exposing three corroded horizontal steel reinforcing bars. The broken piece of the step was lying on the channel bottom and was approximately 3 feet long (E/W).
- The concrete of the bottom portion of the shaft (stepout) at Piers 1 and 2 was frequently soft on the surface with random irregularities and section losses having up to 5 inches of penetration.
- Riprap was observed on the channel bottom measuring 1 to 2 feet in diameter at the upstream nose of Pier 2.
- The shaft bottom step of Pier 2 was cracked and detached at the south eastern corner of Pier 2 with an approximate length of 2.5 feet (E/W) and an approximate width of 8 inches (N/S).
- The bottom portion (stepout) of the concrete shaft was exposed around the entire shaft of Pier 2 with up to full height (1 foot) vertical exposure from the upstream 1/4 point of the south face, around upstream nose to the upstream 1/4 point on the north face. Undermining was observed in the location of full height vertical exposure with a maximum of 0.8 foot height at the upstream nose. The east one ward most steel H-Pile was exposed in the area of undermining with light surface corrosion.
- The concrete of the pier cap and shaft for Pier 1 and 2 were typically smooth and sound with random minor areas of poor consolidation with 1/4 inch maximum penetration and with minor vertical hairline to 1/16 inch wide cracks extending from top pier cap to bottom of lower pier shaft step.
- The bottom portion (stepout) of concrete shaft was exposed around the entire shaft of Pier 1 with up to full height (1 foot) vertical exposure around the entire pier. Undermining was observed in the location of full height vertical exposure with a maximum of 1.4 feet height at the upstream nose. All of the H-Piles were exposed in the area of undermining with light surface corrosion.

Legend

-2.0 Sounding Depth (8/18/07)
-5.2 Sounding Depth (8/26/02)

Timber Debris

Note:

All soundings based on 2007 waterline location.


MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION

STRUCTURE NO. 5750I
OVER THE RED LAKE RIVER
DISTRICT 2, PENNINGTON COUNTY


INSPECTION AND SOUNDING PLAN

Drawn By: PRH	COLLINS ENGINEERS	123 North Wacker Drive Suite 300 Chicago, IL 60606 (312) 704-9300 www.collinsengr.com	Date: AUG. 2007
Checked By: MDK			Scale: NTS
Code: 52210162			Figure No.: I

TYPICAL END VIEW OF PIER



UPSTREAM FASCIA PROFILE



DOWNSTREAM FASCIA PROFILE

Note:
Refer to Figure 1 for General Notes.

MINNESOTA DEPARTMENT OF TRANSPORTATION UNDERWATER BRIDGE INSPECTION		
STRUCTURE NO. 5750I OVER THE RED LAKE RIVER DISTRICT 2, PENNINGTON COUNTY UPSTREAM AND DOWNSTREAM FASCIA PROFILES		
Drawn By: PRH	COLLINS ENGINEERS <small>123 North Wacker Drive Suite 300 Chicago, IL 60606 (312) 704-9300 www.collinsengr.com</small>	Date: AUG. 2007
Checked By: MDK		Scale: 1"=10'
Code: 52210162		Figure No.: 2

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES
DAILY DIVING REPORT

INSPECTORS: Collins Engineers, Inc. DATE: August 18, 2007

ON-SITE TEAM LEADER: Daniel G. Stromberg, P.E.

BRIDGE NO: 57501 WEATHER: Sunny, 69° F

WATERWAY CROSSED: Red Lake River

DIVING OPERATION: X SCUBA SURFACE SUPPLIED AIR
 OTHER

PERSONNEL: John J. Loftus, Valerie Roustan

EQUIPMENT: Scuba, Probe Rod, Lead Line, Camera, U/W Light, Scraper, Sounding Pole,

TIME IN WATER: 11:00 a.m.

TIME OUT OF WATER: 11:40 a.m.

WATERWAY DATA: VELOCITY 1.5 f.p.s.

VISIBILITY 4.0 feet

DEPTH 4.0 feet maximum at Pier 1

ELEMENTS INSPECTED: Piers 1 and 2

REMARKS: The concrete of the pier cap and shaft for Piers 1 and 2 was typically smooth and sound, with random minor areas of poor consolidation with ¼ inch maximum penetration, and with minor vertical hairline to 1/16 inch wide cracks extending from the top of the pier cap to bottom of lower pier shaft step. The bottom portion of the shaft was broken off at the downstream end of Pier 1 exposing three corroded horizontal steel reinforcing bars. The shaft bottom step of Pier 2 was cracked and detached at the southeastern corner of Pier 2. The bottom of shaft step out was exposed around the entire shaft of both piers with up to full height (1 foot) vertical exposure, around the upstream end / nose of both piers. Undermining was observed in the location of full height vertical exposure where the easternmost steel H-piles were exposed with light surface corrosion. There was a light to moderate accumulation of debris and timber drift at the upstream end of Pier 1.

FURTHER ACTION NEEDED: YES X NO

The extent of undermining and foundation pile exposure has been reduced since the last inspection, so based on this current condition and the scour stable (low risk) rating for the bridge, future inspections need only particularly monitor the undermining and pile exposure.

Reinspect the submerged substructure units at the normal maximum recommended (NIBIS) interval of five (5) years.

MINNESOTA DEPARTMENT OF TRANSPORTATION
OFFICE OF BRIDGES AND STRUCTURES

UNDERWATER INSPECTION CONDITION RATING FORM

BRIDGE NO. 57501
INSPECTORS Collins Engineers, Inc.
ON-SITE TEAM LEADER Bradley A. Syler, P.E., S.E.
WATERWAY CROSSED Red Lake River

INSPECTION DATE August 18, 2007

NOTE: USE ALL APPLICABLE CONDITION DEFINITIONS AS DEFINED IN THE MINNESOTA RECORDING AND CODING GUIDE INCLUDING GENERAL, SUBSTRUCTURE, CHANNEL AND PROTECTION, AND CULVERTS AND WALL DEFINITIONS TO COMPLETE THIS FORM.

CONDITION RATING

UNIT REFERENCE NO.	UNIT DESCRIPTION	MAXIMUM DEPTH OF WATER	SUBSTRUCTURE						CHANNEL					GENERAL					
			PILING	COLUMNS, SHAFTS, OR FACES*	FOOTINGS	DISPLACEMENT	OTHER	OVERALL SUBSTRUCTURE CONDITION CODE*	SCOUR	EMBANKMENT EROSION	EMBANKMENT PROTECTION	OTHER (DRIFT/DEBRIS)	OVERALL CHANNEL & PROTECTION CONDITION	CONCRETE	STEEL	TIMBER	LOSS OF SECTION	PREVIOUS REPAIR OR MAINTENANCE	OTHER
		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	Pier 1	4.0'	6	6	4	7	N	5	5	7	8	6	5	5	6	N	5	N	N
	Pier 2	3.5'	6	6	4	7	N	5	5	7	8	N	5	5	6	N	5	N	N

*UNDERWATER PORTION ONLY

REMARKS: The concrete of the pier cap and shaft for Piers 1 and 2 was typically smooth and sound, with random minor areas of poor consolidation with 1/4 inch maximum penetration, and with minor vertical hairline to 1/16 inch wide cracks extending from the top of the pier cap to bottom of lower pier shaft step. The bottom portion of the shaft was broken off at the downstream end of Pier 1 exposing three corroded horizontal steel reinforcing bars. The shaft bottom step of Pier 2 was cracked and detached at the southeastern corner of Pier 2. The bottom of shaft step out was exposed around the entire shaft of both piers with up to full height (1 foot) vertical exposure, around the upstream end / nose of both piers. Undermining was observed in the location of full height vertical exposure where the easternmost steel H-piles were exposed with light surface corrosion. There was a light to moderate accumulation of debris and timber drift at the upstream end of Pier 1.

NOTES: ATTACH SKETCHES AS NEEDED, IDENTIFY REMARK BY REFERRING TO UNIT REFERENCE NO. AND REMARK NO. USE GENERAL SECTION TO IDENTIFY OVERALL PRESENCE OF SPALLS, CRACKS, CORROSION, ETC.